

-1-

# County Surveyor's Record, Douglas County, Oregon

4177

East Bdy. of T. 26 S., R. 3 W.  
 As surveyed by Addison R. Flint, Deputy Surveyor  
 Under Contract No. 56  
 Dated March 1, 1855

CHAINS		
	North on true east boundary of sec. 36 <div style="text-align: right;">Va. 18*E.</div>	
40.00	Set $\frac{1}{4}$ sec. post, from which <div style="margin-left: 40px;">A red fir, 12 ins. diam., bears N.50*E., 24 lks. dist.</div> <div style="margin-left: 40px;">A red fir, 12 ins. diam., bears S.21*W., 52 lks. dist.</div>	+150
66.00	Brook, 5 lks. wide, runs SW	-50
80.00	Set post cor. to secs. 25, 36, 30 & 31, from which <div style="margin-left: 40px;">A red fir, 26 ins. diam., bears S.45*E., 33 lks. dist.</div> <div style="margin-left: 40px;">A red fir, 30 ins. diam., bears N.22*E., 30 lks. dist.</div> <div style="margin-left: 40px;">A laurel, 12 ins. diam., bears S.68*W., 40 lks. dist.</div> <div style="margin-left: 40px;">No trees convenient NW</div>	+60
	Land, 3rd rate, very broken & hilly Timber, principally fir-some oak, pine, cedar, and laurel	
	North on true East boundary of sec. 25 <div style="text-align: right;">Va. 18*15'E.</div>	
20.00	Summit of hill	+75
32.50	Brook, 4 lks. wide, runs SE	-50
40.00	Set $\frac{1}{4}$ sec. post around which a mound of stones was raised as per instructions, no trees convenient	+30
80.00	Set post cor. to secs. 24, 25, 19 & 30, from which <div style="margin-left: 40px;">A laurel, 5 ins. diam., bears N.2*E., 27 lks. dist.</div> <div style="margin-left: 40px;">A laurel, 6 ins. diam., bears N.55*W., 32 lks. dist.</div> <div style="margin-left: 40px;">A R fir, 4 ins. diam., bears S.88*E., 17 lks. dist.</div> <div style="margin-left: 40px;">A R fir, 4 ins. diam., bears S.48*W., 35 lks. dist.</div>	+150
	Land, 3rd rate, rough & hilly Timber principally fir, some oak, cedar, sugar-pine, laurel	
	North on true East boundary of sec. 24 <div style="text-align: right;">Va. 18*E.</div>	
26.00	Brook 5 lks. wide runs SE	-50
40.00	Set $\frac{1}{4}$ sec. post, from which <div style="margin-left: 40px;">A chinquapin, 7 ins. diam., bears East, 14 lks. dist.</div> <div style="margin-left: 40px;">A spruce, 15 ins. diam., bears S.25*W., 15 lks. dist.</div>	+80
66.00	Summit of hill	+150