

## East Bdy. of T. 26 S., R. 3 W.

CHAINS		
80.00	Set post cor. to secs. 18, 19, 13 & 24, from which A laurel, 15 ins. diam., bears S.5*W., 190 lks. dist. A laurel, 12 ins. diam., bears S.17*E., 140 lks. dist. A R fir, 5 ins. diam., bears N.88*W., 10 lks. dist. A R fir, 12 ins. diam., bears N.85*E., 20 lks. dist. Land, 3rd rate, exceedingly rough & mountainous Timber, principally fir, with some oak, cedar, sugar-pine and laurel	-50
20.00	North on true East boundary of Sec. 13 Va. 18*15*E.	-1500
30.00	Foot of steep hill	
40.00	Set $\frac{1}{2}$ post on side hill, from which A R fir, 96 ins. diam., bears S.20*W., 22 lks. dist. A hemlock, 10 ins. diam., bears S.47*E., 12 lks. dist.	-300
51.75	Brook 15 lks. wide runs NE	-200
80.00	Set post cor. to secs. 7, 18, 12 & 13, from which A hemlock, 6 ins. diam., bears S.1*E., 27 lks. dist. A hemlock, 5 ins. diam., bears S.20*W., 39 lks. dist. A hemlock, 6 ins. diam., bears N.40*W., 16 lks. dist. A cedar, 25 ins. diam., bears N.60*E., 23 lks. dist. Land, 3rd rate, exceedingly rough and mountainous Timber, usually fir, some cedar, sugar-pine, oak & laurel	-200
18.10	North on true East boundary of sec. 12 Va. 19*E. Brook, 12 lks. wide, runs NE Falls at the place of crossing Estimated at 50 ft.	-200