

- 48 -
County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 26 S., R. 2 W.

CHAINS

General Description:

The general character of the land in this Township is mountainous. The S. W. portion is too mountainous to be surveyed and is unfit for settlement.

Densely covered with forests of fir, hemlock, cedar, pine, maple, alder, yew, chinquapin, laurel & dogwood, with a thick undergrowth of sallah, vine-maple, hazel, fir, manzanits, laurel, salmon-berry and huckleberry.

Xavier Plant has a claim in sec. 23 with a house and barn.

Subdivisions of T. 26 S., R. 2 W.
Surveyed by William N. Gibb, Deputy Surveyor
Under Contract No. 783, dated December 3, 1908

Then at cor. secs. 34, 35, 2 and 3, which is a stake greatly decayed, marked and witnessed as described by the Surveyor General,

Set granite stone, 8x10x14 ins., 10 ins. in the ground for cor. secs. 34, 35, 2 and 3, marked with 4 notches on W. and 2 notches on E. edge.

Thence I run

N.1'W. on true line bet. secs. 34 and 35 through ^{dense} underbrush and heavy timber; ascend S. slope.

27.00 Top of ridge, bears E. and W.; descend NE slope.

40.00 Set granite stone, 5x9x14 ins., 10 ins. in the ground for

$\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W. face, from which

A cedar, 50 ins. diam., bears N.54*E., 36 lks. dist.

Marked $\frac{1}{4}$ S 35 B T

A fir, 8 ins. diam., bears S.74*W., 24 lks. dist.

Marked $\frac{1}{4}$ S 34 B T

On top of ridge, bearing E and W; descend N. slope.

49.00 Creek, 2 lks. wide, flows E; ascend SE slope

54.00 Top of ridge, bears E and W descend E slope

61.00 Creek, 2 lks. wide, flows SE; ascend E slope

80.00 Set granite stone, 8x10x14 ins., 10 ins. in the ground

for cor. secs. 26, 27, 34 and 35, marked with 2 notches