

## Subdivisions of T. 26 S., R. 2 W.

CHAINS	<p>A laurel, 5 ins. diam., bears S.42*W., 20 lks. dist.          Marked T 26 S R 2 W S 35 B T</p> <p>A fir, 8 ins. diam., bears N.62*W., 30 lks. dist.          Marked T 26 S R 2 W S 26 B T</p> <p>I destroy markings on old cor. referring to secs. 26 and 35</p> <p>Thence I run</p> <p>W. on true line bet. secs. 26 and 35; ascend S. slope through dense underbrush and heavy timber.</p>
40.00	<p>Set sandstone, 6x10x15 ins., 10 ins. in the ground for <math>\frac{1}{4}</math> sec. cor., marked <math>\frac{1}{4}</math> on N face, from which</p> <p>A cedar, 18 ins. diam., bears N.48*W., 21 lks. dist.          Marked <math>\frac{1}{4}</math> S 26 B T</p> <p>A fir, 30 ins. diam., bears S.18*E., 35 lks. dist.          Marked <math>\frac{1}{4}</math> S 35 B T</p> <p>Descend W. slope.</p>
71.20	<p>Cor. secs. 26, 27, 34 and 35</p> <p>Land, mountainous</p> <p>Soil, rocky; 4th rate</p> <p>Timber, cedar, fir, matherone and hemlock.</p> <p>Underbrush, young firs, rhododendrons and vine-maple.</p> <p>Land, mountainous, covered with dense underbrush and heavily timbered and exceptionally difficult to survey,          71.20 chs.</p>
40.07	<p>Thence from the cor. secs. 25, 26, 35 and 36,          I retrace S. bet. secs. 35 and 36</p> <p>Gr. sec. cor., which is a stake greatly decayed, marked as described by the Surveyor General</p> <p>Bearing trees have been destroyed.</p> <p>Set granite stone, 6x10x15 ins., 10 ins. in the ground for <math>\frac{1}{4}</math> sec. cor., marked <math>\frac{1}{4}</math> on W. face, from which</p> <p>A fir, 12 ins. diam., bears N.75*E., 26 lks. dist.          Marked <math>\frac{1}{4}</math> S 36 B T</p>