

## Subdivisions of T. 26 S., R. 2 W.

## CHAINS

Bearing trees have been destroyed.

Set granite stone, 8x10x14 ins., 10 ins. in the ground for cor. secs. 19, 24, 25 and 30, marked with 4 notches on N and 2 notches on S edge, from which

A fir, 8 ins. diam., bears N.52\*E., 27 lks. dist.

Marked T 26 S R 2 W S 19 B T

A fir, 8 ins. diam., bears S.14\*E., 26 lks. dist.

Marked T 26 S R 2 W S 30 B T

A laurel, 6 ins. diam., bears S.10\*W., 16 lks. dist.

Marked T 26 S R 3 W S 25 B T

A fir, 6 ins. diam., bears N.18\*W., 18 lks. dist.

Marked T 26 S R 3 W S 24 B T

Thence I retrace

N. bet. secs. 19 and 24

40.02

Qr. sec. cor., which is a stake greatly decayed, marked and witnessed as described by the Surveyor General

Bearing trees have been destroyed.

Set hemlock stake, 3 ft. long, 4 ins. sq. 24 ins. in the ground for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S 24 on W, and 19 on E face, from which

A laurel, 10 ins. diam., bears S.21\*W., 10 lks. dist.

Marked  $\frac{1}{4}$  S 24 B T

A laurel, 10 ins. diam., bears N.69\*E., 13 lks. dist.

Marked  $\frac{1}{4}$  S 19 B T

80.04

Cor. secs. 13, 18, 19 and 24, which is a stake greatly decayed, marked as described by the Surveyor General

Bearing trees have been destroyed.

Set granite stone, 7x11x15 ins., 10 ins. in the ground for cor. secs. 13, 18, 19 and 24, marked with 4 notches on N and S edges, from which

A fir, 24 ins. diam., bears N.53\*E., 108 lks. dist.

Marked T 26 S R 2 W S 18 B T

A fir, 24 ins. diam., bears S.80\*E., 31 lks. dist.

Marked T 26 S R 2 W S 19 B T