

Subdivisions of T. 26 S., R. 2 W.

CHAINS

I destroy markings on other cor. referring to secs. 19,
20

Thence I run

S.4'E., on true line bet. secs. 19 and 20, through dense
underbrush and heavy timber, ascend North slope

13.04 Set granite stone, 6x8x12 ins., 8 ins. in the ground for
 $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on West face, from which

A maple, 6 ins. diam., bears S.80*30'E., 10 lks.
dist. Marked $\frac{1}{4}$ S 20 B T

A fir, 20 ins. diam., bears N.86*15'W., 51 lks. dist.
Marked $\frac{1}{4}$ S 19 B T

20.00 Top of ridge, bears E and W, descend South slope

53.04 Cor. secs. 19, 20, 29 and 30

Land, mountainous

Soil, rocky, 4th rate

Timber, cedar, hemlock, yellow pine and fir

Underbrush, vine maple, rhododendrons and young firs.

Land, mountainous, covered with dense underbrush and
heavily timbered and exceptionally difficult to survey
53.04 chs.

July 4, 1910.

Retracement-Reestablishment of the
North and Portions of South, East and West Bdrs.
of
Township No. 26 South, Range No. 2 West,
By Charles M. Collier, U. S. Surveyor
Under Instructions dated May 12, 1913, Sept. 23, 1913

Retracement- Reestablishment
Portion of W. Bdy. of T. 26 S., R. 2 W.

May 29: I commence at the cor. of secs. 13, 18, 19 and 24,
on the W. bdy. of the Tp., which is a granite stone,
firmly set, marked and witnessed as described by the
surveyor general.

Thence I run

North, retracing the W. bdy. of sec. 18