

County Surveyor's Record, Douglas County, Oregon

Retracement-Reestablishment
Portion of W. Bdy. of T. 26 S., R. 2 W.

CHAINS	
	Descend steep NW slope through heavy timber
17.60	Foot of steep descent
	Thence over bench land, sloping gently to the N
38.95	Fall 96 lks. E. of the point for $\frac{1}{4}$ sec. cor., located by
	reference to the SW. bearing tree, which is a red fir,
	marked as described by the surveyor general; all other
	traces of the cor. have been obliterated. I reestablish
	this cor. in its original position, as follows:
	Set a basalt stone, 12x8x6 ins., 8 ins. in the ground, for
	$\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on W. face; from which
	A red fir, 96 ins. diam., bears S.20*W., 22 lks. dist.
	Marked $\frac{1}{4}$ S B T (Original bearing tree).
	The true course and distance of this line is N.1*25'W.,
	38.96 chs.
	May 29, 1913
	Thence I run
	North, counting distance from sec. cor.
	Descend steep N. slope
50.47	Stream 10 lks. wide, course NE; ascend
64.93	Top of ridge, bears NE and SW; descend over gradual North
	slope
79.64	Fall 72 lks. W. of the point for the cor. of secs. 7, 12,
	13 and 18, located by reference to the bearing trees,
	which are as described by the surveyor general; all
	traces of the cor. have disappeared. I re-establish
	this cor. in its original position, as follows:
	Set a basalt stone, 14x10x8 ins., 9 ins. in the ground,
	for cor. of secs. 7, 12, 13 and 18, marked with 2 notches
	on North and 4 notches on South edge; from which the orig-
	bearing trees bear as follows:
	A cedar, 25 ins. diam., bears N.60*E., 23 lks. dist.
	Marked T 26 S R 2 W S 7 B T
	A hemlock, 12 ins. diam., bears S.1*E., 27 lks. dist.
	Marked T 26 S R 2 W S 18 B T