

Retracement-Reestablishment
Portion of W. Bdy. of T. 26. S., R. 2 W.

CHAINS

This cor. stands at head of steep ravine, course W
Creek

Rock¹ is about 12 chs. to the west

The true course and distance of this line from the $\frac{1}{4}$ sec.
cor. is North, 40.05 chs.

Sky overcast at noon, latitude observation impossible

Note:

Survey postponed pending action and the issuance of
Supplemental Special Instructions based on the report of
my preliminary examination as to the condition of old sur-
veys in this township.

May 31, 1913.

Survey resumed October 25, 1913.
Thence I run

South, retracing the line bet. secs. 25 and 30.

Descend gradual slope through heavy timber and dense under-
growth.

4.35 Stream, 2 lks. wide, course E.; ascend

13.18 Trail, bears E and W.

40.01 Fall 51 lks. W. of the $\frac{1}{4}$ sec. cor., which is a fir post,
firmly set, marked and witnessed as described by the
surveyor general.

This is probably not the original cor. post, but it is set
in the original mound of stone and was evidently placed
there to perpetuate the old cor., which had become de-
cayed.

The true course and distance of this line is S.0°44'E.,
40.01 chs.

I continue my line South from the $\frac{1}{4}$ sec. cor., counting
distance from the sec. cor.

43.73 Bottom of ravine, course S.80°E.

63.84 Trail, bears E and W.

77.65 Keolin prospect shaft, bears W., 20 lks. dist.

79.88 Fall 50 lks. W. of the point for cor. of secs. 25, 30, 31
and 36, located by reference to the bearing trees as
described by the surveyor general; all other traces of