

Retracement-Reestablishment
Portion of S. Bdy. of T. 26 S., R. 2 W.

CHAINS

Land, hilly
Soil, clayey loam, 2nd rate
Timber, heavy stand of fir, cedar and pine on E. 20.00
chs., scattering on W part.
Undergrowth, thicket of fir and laurel throughout

East, retracing the S. bdy. of sec. 32.

Descend SE slope through dense young timber

9.71 Stream, 7 lks. wide, course SE; ascend

20.20 Cliff, 30 ft. high, facing SW; thence along S. slope.

27.71 Stream, 2 lks. wide, course S.

36.57 Stream, 4 lks. wide, course S

39.45 Fall 3 lks. N. of the $\frac{1}{4}$ sec. cor., which is a cedar post
firmly set, marked and witnessed as described by the
surveyor general.

The true course and distance of this line is S.89°57'E.,
39.45 chs.

I continue my measurements

East, from the $\frac{1}{4}$ sec. cor., counting distance from sec.
cor.

Along S slope

56.16 Stream, 1 lk. wide, course S

60.00 Enter dense fir thicket, bears N and S

67.00 Descend

76.54 A stream, 1 lk. wide, course S; ascend

79.81 Fall 10 lks. S. of the cor. of secs. 4, 5, 32 and 33,
which is a cedar post, firmly set, marked and witnessed
as described by the surveyor general. Elevation at this
cor. 2634 ft.

The true course and distance of this line from the $\frac{1}{4}$ sec.
cor. is N.89°52'E., 40.36 chs.

Land, hilly

Soil, clayey loam, 2nd rate