

Retracement-Reestablishment
E. Bdy. of Secs. 1, 12 and 13, T. 26 S., R. 2 W.

CHAINS	
40.34	<p>The $\frac{1}{4}$ cor. of sec. 13 only, which is a basalt stone, firmly set, marked and witnessed as described by the surveyor general, bears West, 5 lks. dist.</p> <p>Elevation at this cor. 1600 ft.</p> <p>The true course and distance of this line is N.0°43'E., 40.34 chs.</p> <p>From the $\frac{1}{4}$ sec. cor., I run</p> <p>N.4°08'W., counting distance from the sec. cor.</p>
52.14	<p>Begin steep ascent of rocky SE slope, through heavy fir timber and dense undergrowth.</p>
67.34	<p>Over bench land, bears NE and SW</p>
71.34	<p>Leave bench land; begin very steep ascent</p>
75.08	<p>The closing cor. of secs. 7 and 13, which is a cross (x) on a conglomerate rock in place, marked and witnessed as described by the surveyor general, bears East, 38 lks. dist.</p>
79.08	<p>The cor. of secs. 12 and 13, which is a basalt stone, firmly set, marked and witnessed as described by the surveyor general, bears East, 44 lks. dist.</p> <p>Elevation 2326 ft.</p> <p>The true course and distance of this line from the $\frac{1}{4}$ sec. cor. is N.3°30'W., 38.74 chs.</p> <p>Land, mountain benches and steep slopes.</p> <p>Soil, on benches deep clayey loam, on slopes rocky; 2nd and 4th rate</p> <p>Timber, fir, cedar and sugar pine</p> <p>Undergrowth, dense buckbrush, greasewood and maple</p>
1.00	<p>N.0°48'E., retracing the E. bdy. of sec. 12</p> <p>Ascend very steep slope</p> <p>Basalt bluffs, facing S.; shelves covered with rank grass</p>
7.00	<p>Top of bluffs; enter scattering old growth of firs with dense fir thicket.</p> <p>Thence ascend gradually over hilly bench with general E. slope.</p>