

Retracement-Reestablishment  
E. Bdy. of Secs. 1, 12 and 13, T. 26 S., R. 2 W.

CHAINS

The true course and distance of this line from the  $\frac{1}{4}$  sec. cor. is North, 39.17 chs.

Land, rolling

Soil, good clayey loam; 2nd rate

Timber, heavy growth of fir, cedar and sugar pine

Undergrowth, rhododendron, greasewood and chinquapin.

December 18, 1913.

Retracement-Reestablishment of N. Bdy. of T. 26 S., R. 2 W.

From the cor. of Tps. 25 and 26 S., R. 2 W., on W. bdy. of T. 26 S., R. 1 W., I run

N.89°47'W., retracing the N. bdy. of sec. 1.

Ascending E. slope through dense brush with some old growth of fir.

14.69 Broad top of divide, bears NE and SW., with open glades and fir groves.

Elevation 4100 ft.

Descend steep NW slope through dense fir thicket.

38.78 Fall 15 lks. N. of the point for  $\frac{1}{4}$  sec. cor. of sec. 1, located by reference to the bearing trees as described by the surveyor general: All other traces of the cor. have disappeared. I re-establish this cor. in its original position, as follows:

Set a basalt stone, 18x10x8 ins., 12 ins. in the ground, for  $\frac{1}{4}$  sec. cor. of sec. 1 only, marked  $\frac{1}{4}$  on N face, witnessed by the original bearing trees as follows:

A fir, 36 ins. diam., bears N.60°E., 35 lks. dist.

The facing was only in the bark and is nearly burned away.

A fir, 36 ins. diam., bears S.5°W., 67 lks. dist.

Marked (in the bark)  $\frac{1}{4}$  S B T

The true course and distance of this line is West, 38.78 chs.