

Retracement-Reestablishment of N. Bdy. of T. 26 S., R. 2 W.

CHAINS

I continue my retracement of line.

N.89°47'W., from the $\frac{1}{4}$ sec. cor., counting distance from sec. cor.

42.06 Stream, 2 lks. wide, course SW

Elevation at this point 3340 ft.

Thence ascending along general S. slope through old burn with dense fir and greasewood undergrowth.

49.42 Top of ascent on S slope

Descend W slope

72.31 Stream, 10 lks. wide, course SW

73.84 Stream, 15 lks. wide, course S. These are heads of Susan Creek; they join about 2.00 chs. below

Elevation 2960 ft.

Ascend steep side of canyon.

78.00 Fall 35 lks. S. of the point for the cor. of Secs. 1 and 2, located by reference to the original fir bearing tree, 50 ins. diam., bearing N.55°E., 20 lks. dist.; it had been faced in the bark and fire has swept it, but some traces of the markings are to be seen and this is the only tree of such size that has stood in this vicinity for more than 30 years. Some 30 year old blazes were found also, just E. of the two streams, on line leading to this point; all other bearing trees and the original post are entirely destroyed. At the cor. point so determined, I

Set a cedar post, 3 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. of secs. 1 and 2 only, marked T 26 S S 1 on SE and R 2 W S 2 on SW face, with 1 notch on E. and 5 notches on W. edge, from which

A fir, 8 ins. diam., bears S.44°E., 101 lks. dist.

Marked T 26 S R 2 W S 1 B T

A fir, 6 ins. diam., bears S.38°W., 217 lks. dist.

Marked T 26 S R 2 W S 2 B T