

Retracement-Reestablishment of N. Bdy. of T. 26 S., R. 2 W.

CHAINS

Undergrowth, dense young chinquapin, willow and cherry with grass, ferns and briars covering all openings, forming good pasture.

Elevation 3300 ft.

From temp. cor. of secs. 3 and 4, I run N.89°47'W., retracing the N. line of sec. 4. On high table land in old burn.

4.00 Cross divide bet. North Umpqua and Rock Creek Drainages, bears NE and SW. There is a low gap in this divide, about 20.00 chs. to SW.

4.62 Search for the closing cor. of secs. 33 and 34, but find no trace thereof.

11.98 Begin steep descent on NW slope

22.00 Enter fir and sugar pine timber with dense fir thicket undergrowth, bears N and S.

31.30 Foot of steep descent; thence over bench with general N. slope.

36.15 Fall 40 lks. S. of the $\frac{1}{4}$ sec. cor. on N. line of sec. 4, where I find remains of old post, marked and witnessed as described by the surveyor general. The post almost decayed. I destroy this cor. and re-establish it in the same place, as follows:

Set a cedar post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor. of sec. 4 only, marked $\frac{1}{4}$ S 4 on S. face, witnessed by the original bearing trees, as follows:

A cedar, 10 ins. diam., bears N.30°E., 16 lks. dist.

Marked $\frac{1}{4}$ SB T

A cedar, 16 ins. diam., bears S.20°W., 30 lks. dist.

Marked $\frac{1}{4}$ S B T

The true course and distance of this line from the cor. of secs. 1 and 2 is N.89°40'W., 196.15 chs.

Elevation 2800 ft.