

Resurvey of Portion of East Bdy., T. 26 S., R. 2 W.

CHAINS

40.00 Top of ascent; thence over nearly level bench.

55.72 Intersect the original McQuinn cor. established in 1883 as the cor. of secs. 25, 30, 31 and 36 and reestablished in 1910 by Deputy Mensch as the cor. of secs. 25 and 36 only, which is a basalt stone, 15x10x8 ins., firmly set, marked and witnessed as described by the surveyor general. I now remove the old stone (set by Deputy Mensch in place of the original cor., a post) and in its place Set an iron post, 3 ft. long, 3 ins. diam., 24 ins. in the ground, for cor. of secs. 25 and 36, with brass cap marked

T26S	
S25	
S36	
R2W	
	1916

from which

A fir, 30 ins. diam., bears S.40*W., 31 lks. dist.

Marked T 26 S R 2 W S 36 B T

A cedar, 48 ins. diam., bears N.40*W., 18 lks. dist.

Marked T 26 S R 2 W S 25 B T

I destroy the corresponding cor. of the rejected revision survey and marks on bearing trees.

Note:

At 40.00 chs. distance from each sec. cor. of this line, and along the intervening space, I search carefully for evidence of McQuinn's $\frac{1}{4}$ sec. cor. or his line, but find no traces.

Land, mountainous

Soil, stony clay loam, 3rd rate

Timber, fir, hemlock and cedar

Undergrowth, madrons, snowbrush, vine maple and hazel

N.0*22'E., resurveying the original McQuinn line established in 1883, along E. bdy. of sec. 25.

Over mountainous land, through dense timber and undergrowth