

Resurvey of Portion of East Bdy., T. 26 S., R. 2 W.

CHAINS	
	<p>firmly set, marked and witnessed as described by the survey general) bears N.40*27'W., 80 lks. dist. I now destroy this cor. and marks on bearing trees.</p> <p>Thence N.0*53'W., along E. bdy. of sec. 25, continuing my measurements bet. McQuinn cors.</p>
48.00	Foot of steep descent, on bench of mountain.
49.36	<p>To a point from which the $\frac{1}{4}$ cor. of sec. 30, T. 26 S., R. 1 W. (established by Deputy Mensch in 1910, which is a basalt stone, 15x12x10 ins., firmly set, marked and witnessed as described by the surveyor general) bears N.89*42'W., 52 lks. dist.</p> <p>To this point I now move the original stone, which I set 10 ins. in the ground, for $\frac{1}{4}$ cor. of sec. 30, marked $\frac{1}{4}$ on E. face; from which</p> <p style="padding-left: 40px;">A cedar, 18 ins. diam., bears N.49*E., 25 lks. dist. Marked $\frac{1}{4}$ S 30 B T</p> <p style="padding-left: 40px;">A cedar, 14 ins. diam., bears S.60*E., 55 lks. dist. Marked $\frac{1}{4}$ S 30 B T</p> <p>I destroy marks on bearing trees at former cor.</p>
54.00	Begin descent of steep N. slope
57.27	Trail, bears E. and W.
64.00	Creek, 2 lks. wide, course NE.; descend NE. slope
72.40	Steep point, slopes E.
77.00	Trail, bears NW and SE.
84.59	<p>Intersect the original McQuinn cor. established in 1883 the cor. of secs. 19, 24, 25 and 30, which point is now marked by a basalt stone, set at proper point as indicated by the bearing trees, which are as described by the surveyor general, except that the SW. and NW. bearing trees are dead and now unfit for further use.</p> <p>I now perpetuate this cor. as the cor. of secs. 24 and 25 only, by setting, at exact cor. point, an iron post, 3</p>