

122
County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS	
	<p>A fir, 36 ins. diam., bears N.50*E., 40 lks. dist. Marked T 26 S R 2 W S 24 B T (Orig. B.T.)</p> <p>A chinquapin, 10 ins. diam., bears S.50*E., 22 lks. dist. Marked T 26 S R 2 W S 25 B T (Orig. B.T.)</p> <p>A chinquapin, 10 ins. diam., bears S.30*W., 30 lks. dist. Marked T 26 S R 2 W S 26 B T (Orig. B.T.)</p> <p>A chinquapin, 8 ins. diam., bears N.20*W., 21 lks. dist. Marked T 26 S R 2 W S 23 B T (Orig. B.T.)</p> <p>I destroy the corresponding cor. of the rejected revision survey and marks on bearing trees.</p> <p>Land, mountainous</p> <p>Soil, stony clay loam, 3rd rate</p> <p>Timber, fir, cedar, hemlock, chinquapin and sugar pine</p> <p>Undergrowth, hemlock, fir, rhododendron and vine maple</p>
	<p>S.88*41'E., resurveying the line bet. secs. 24 and 25</p> <p>Over mountainous land, through dense timber and undergrowth</p> <p>Descend E slope</p>
1.75	Begin steep descent
9.45	Creek, 8 lks. wide, course NE
10.45	Creek, 5 lks. wide, course N, ascend steep NW slope
17.00	Ascend bluff, 60 ft. high
20.00	Top of steep slope, continue ascent
27.60	Creek, 1 lk. wide, course N, ascend steep NW slope
33.70	Ascend bluff, 25 ft. high
35.20	Spur, slopes NW, descend NE slope
39.10	Creek, 2 lks. wide, course NW, ascend W slope
42.31	<p>Intersect the original $\frac{1}{4}$ sec. cor., established by Deputy McQuinn in 1883 and not reported found in any subsequent survey. The old post is found, badly decayed, witnessed as described by the surveyor general, except that the S bearing tree is down. I now perpetuate this cor., as follows: at the exact cor. point</p>