

County Surveyor's Record, Douglas County, Oregon

Resurvey of Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS	<p>Land, rolling</p> <p>Soil, stony clay loam, 3rd rate</p> <p>Timber, fir, cedar, sugar pine and hemlock</p> <p>Undergrowth, hazel, vine maple, hemlock and fir</p> <hr/> <p>I return to the cor. of secs. 23, 24, 25 and 26, heretofore described</p> <p>Thence</p> <p>S.86*37'W., resurveying the line bet. secs. 23 and 26</p> <p>Over mountainous land, through dense timber and undergrowth</p> <p>Ascend E slope</p> <p>8.00 Top of ascent; thence broken N slope</p> <p>17.00 Creek, 1 lk. wide, course N</p> <p>22.00 Creek, 1 lk. wide, course NW</p> <p>23.25 Creek, 3 lks. wide, course N</p> <p>34.75 Descend bluff, 90 ft. high, bears NE and SW, continue descent on steep rocky NW slope</p> <p>40.00 Foot of steep slope; continue descent</p> <p>40.35½ (Midpoint) Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for ¼ sec. cor., with brass cap marked</p> <div style="text-align: center; margin: 10px 0;"> $\frac{1}{4} \begin{array}{l} S23 \\ S26 \\ 1916 \end{array}$ </div> <p>from which</p> <p style="padding-left: 40px;">A cedar, 16 ins. diam., bears N.23*E., 4 lks. dist.</p> <p style="padding-left: 80px;">Marked ¼ S 23 B T</p> <p style="padding-left: 40px;">A cedar, 24 ins. diam., bears S.25*E., 5 lks. dist.</p> <p style="padding-left: 80px;">Marked ¼ S 26 B T</p> <p>I destroy the corresponding cor. of the rejected revision survey and marks on bearing trees.</p> <p>57.75 Creek, 3 lks. wide, course NW, ascend steep NE slope</p> <p>63.50 Spur, slopes NE, descend NW slope</p> <p>66.90 Creek, 2 lks. wide, course NE, ascend steep E slope</p>
--------	---