

Retracement and Resurvey of Subdivisional Lines, T. 26 S., R. 2 W.

CHAINS

40.00 Fall 19 lks. W of the $\frac{1}{4}$ cor. bet. secs. 19 and 20, established by Deputy Gibb in 1910, which is a granite stone, 4x8x6 ins. above ground, firmly set, marked and witnessed as described by the surveyor general

The true course and length of this line is N.0°12'E., 40.00 chs.

Thence

North, from the $\frac{1}{4}$ cor., continuing my measurements, resurveying the line bet. secs. 19 and 20

Over mountainous land, through dense timber and undergrowth

Descend steep N slope

41.20 Foot of steep descent; thence over bench, gently sloping to West

46.60 Begin descent of steep rocky NW slope

52.32 Intersect the closing cor. of secs. 19 and 20, established by me in 1916, which is an iron post, 3 ft. long, 2 ins. diam., 12 ins. above ground, marked and witnessed as described by the surveyor general. I now destroy this cor.

Descend gradual NW slope

65.50 Top of spur, slopes NW; descend N slope

67.28 Intersect new S bdy. of sec. 17, 4.05 chs. N.87°04'E. of cor. of secs. 17 and 18, heretofore described

At the point of intersection

Set an iron post, 3 ft. long, 2 ins. diam., 24 ins. in the ground, for closing cor. of secs. 19 and 20, with brass cap marked

T26SR2W	
S17	
S19	S20
T26S	R2W
CC	
1918	

from which

A cedar, 12 ins. diam., bears S.18°E., 37 lks. dist.

Marked C C T 26 S R 2 W S 20 B T