

Survey of Tracts 37 and 38, T. 26 S., R. 2 W.

CHAINS	
8.25	Ravine, course NE
13.75	Creek, 4 lks. wide, course SE; ascend W slope
18.00	Top of spur, slopes S; descend SE slope
21.00	Creek, 4 lks. wide, course S; ascend SW slope
31.50	Ravine, course S
40.00	Set an iron post, 3 ft. long, 1 in. diam., 26 ins. in the ground, for cor. No. 4 of Tract 38, with brass cap marked

TR 38 T26S  
 4 R2W  
 S35  
 1918

from which

A cedar, 14 ins. diam., bears N.8\*W., 31 lks. dist.

Marked 4 TR 38 B T

Land, mountainous

Soil, stony clay loam, 3rd rate

Timber, fir, hemlock and cedar

Undergrowth, arrowwood, hazel and chinquapin

20.00	<p>North on E bdy. of Tract 38</p> <p>Ascend S slope, through heavy timber and dense undergrowth</p> <p>Intersect cor. No. 1 of Tract 38, the place of beginning,</p> <p>Land, mountainous</p> <p>Soil, stony clay loam, 3rd rate</p> <p>Timber, fir, hemlock and cedar</p> <p>Undergrowth, chinquapin, hazel and arrowwood</p>
-------	---

General Description

The portion of the township affected by this survey is in general of a rough mountainous character, with some benches and gentle slopes suitable for agriculture. The soil on these benches appears to be of good quality as far as determined.

The tract is fairly well timbered, except in burned over areas. The timber is principally fir and hemlock, with some cedar and sugar pine.

There are a number of settlers claiming residence on the