

East Boundary of T. 26 S., R. 4 W.  
 As surveyed by Addison R. Flint, Deputy Surveyor  
 Under contract No. 56, dated March 1, 1855.

CHAINS		
	Began at the post, the established SE cor. of tp. 25 S in R 4 W, and ran S on the E bdy. of sec. 1. <div style="text-align: right;">Va.18*30'E.</div>	
16.50	Brook, 8 lks. wide, runs E.	-50
17.75	Cedar, 28 ins. diam.,	
31.00	Summit of hill.	+100
40.00	Set $\frac{1}{4}$ sec. post, from which <div style="margin-left: 40px;">A laurel, 15 ins. diam., bears N.85*E., 45 lks. dist.,</div> <div style="margin-left: 40px;">A laurel, 8 ins. diam., bears S.57*W., 38 lks. dist.</div>	+20
55.00		-50
	Va.19*E.	
65.00	Summit of hill.	+75
78.00	Ravine, NW.	-80
80.00	Set post, cor. to secs. 1, 12, 6 and 7, from which <div style="margin-left: 40px;">A red fir, 15 ins. diam., bears N.10*W., 83 lks. dist.</div> <div style="margin-left: 40px;">A red fir, 23 ins. diam., bears N.37*E., 100 lks. dist.</div> <div style="margin-left: 40px;">A laurel, 7 ins. diam., bears S.51*E., 145 lks. dist.</div> <div style="margin-left: 40px;">A laurel, 5 ins. diam., bears S.43*W., 187 lks. dist.</div>	+50
	Land, 3d rate. Timber, fir, cedar, pine, oak and laurel.	
	South, on East bdy. of sec. 12. <div style="text-align: right;">Va.17*15'E.</div>	
15.00	Summit of hill.	+75
20.00	Left fir timber.	-40
35.00	Trail, NE.	-80
40.00	Set $\frac{1}{4}$ sec. post, from which	+15