

Subdivisions and Meanders of Umpqua River in Township 26 S.,
 R 4 W., W. M.

CHAINS	S.89°43'W., on true line between Secs. 3 & 10.
40.00	Set $\frac{1}{4}$ Sec. post from which, A B. Oak, 16 ins. dia., bears S.25°E., 528 lks. dist. A R. Oak, 14 ins. dia., bears N.51°E., 150 lks. dist.
80.00	To post corner of Secs. 3, 4, 9, & 10. Land, rolling and second rate. Timber, scattering oak.
	Va. 18°30'E.
	North, on random between Secs. 3 & 4.
19.00	Summit of ridge, N.E. & S.W.
	Va. 21°E.
40.00	Set temporary $\frac{1}{4}$ Sec. post
45.00	Creek 10 lks. wide. Course, S. W.
80.58	Intersected E. & W. township line, 28 lks. west of post corner of Secs. 3 & 4, from which corner, I run, S.12°W., on true line between Secs. 3 & 4.
40.29	Set $\frac{1}{4}$ Sec. post from which, A B. Oak, 12 ins. dia., bears West, 5 lks. dist. A B. Oak, 20 ins. dia., bears S.70°E., 50 lks. dist.
80.50	To post corner of Secs. 3, 4, 9, & 10. Land, good grazing, but too undulating for agriculture. Timber, a few scattering oaks and laurel.
	Va. 18 $\frac{1}{2}$ °E.
	North, on true line between Secs. 32 & 33.
35.00	Enter prairie.
40.58	Set $\frac{1}{4}$ Sec. post from which, An Ash, 10 ins. dia., bears N.60°W., 148 lks. dist. An Ash, 16 ins. dia., bears N.82 $\frac{1}{2}$ °W., 53 lks. dist. (No trees convenient on East side of line)
44.50	Enter Improvements. Fence E. & W.
57.00	Left improvements.
68.00	Leave prairie.
70.30	Observed H. J. Oden's house. N.86°W.
80.00	Observed H. J. Oden's house. S.46°W.