

3/
County Surveyor's Record, Douglas County, Oregon

Subdivisions and Meanders of Umpqua River in Township 26S.,
R. 4 W., W. M.

CHAINS	
	Va. 20 $\frac{1}{2}$ *E.
	North, on line between Secs. 8 & 9.
11.50	Foot of hill. N. E.
15.00	Summit of hill.
34.00	Foot of hill.
37.00	To creek, 15 lks. wide. Course S. W.
40.00	Set $\frac{1}{4}$ Sec. post from which, <div style="margin-left: 40px;">A W. Oak, 15 ins. dia., bears N.60*W., 362 lks. dist.</div> <div style="margin-left: 40px;">A W. Oak, 18 ins. dia., bears N.54*E., 285 lks. dist.</div>
52.00	Var. 15*30'E.
62.00	Var. 18*30'E.
80.00	Set post corner to Secs. 4, 5, 8 & 9, and there being no trees near, raised mound as per instructions. Land, 2nd rate, broken & hilly, good grazing. Timber, a few scattering oak trees.
	East, on random between, secs. 4 & 9.
32.50	To foot of hill. Va. 18*E.
36.00	Creek 15 lks. wide, course S. W.
38.00	Foot of ridge, N. E. & S. W.
40.00	Set $\frac{1}{4}$ Sec. post from which, <div style="margin-left: 40px;">A B. Oak, 15 ins. dia., bears N.75*E., 164 lks. dist.</div> <div style="margin-left: 40px;">A W. Oak, 8 ins. dia., bears S.40*W., 130 lks. dist.</div>
62.00	Summit of hill. N.E. & S.W. Va. 21*E.
79.50	Intersected N. & S. line., 16 lks. north of post corner to secs. 3, 4, 9, & 10, from which corner I run, West, on true line between Secs. 4 & 9.
39.75	Set $\frac{1}{4}$ Sec. post from which, <div style="margin-left: 40px;">A B. Oak, 15 ins. dia., bears N.75*E., 164 lks. dist.</div> <div style="margin-left: 40px;">A W. Oak, 8 ins. dia., bears S.40*W., 130 lks. dist.</div>
79.50	To post corner of Secs. 4, 5, 8 & 9. Land, 2nd rate. Good pasturage, too broken for agriculture. Timber, A very few oak trees.