

35

## County Surveyor's Record, Douglas County, Oregon

Subdivisions and Meanders of Umpqua River in Township 26 S.,  
R. 4 W., W. M.

CHAINS		
77.20	To post corner of Secs. 19, 20, 29 & 30. Land, 2nd rate. Timber, fir oak & Laurel.	
	Va. 25*E.	
	North, on line between Sec. 19 & 20.	
24.00	Summit of hill.	Va. 14*30'E.      •200
23.00	Ridge. E. & W.	Va. 19½*E.
40.00	Set ¼ Sec. post, from which , A W. Oak, 26 ins. dia., bears S.21*W., 200 lks. dist. A W. Oak, 12 ins. dia., bears S.36*E., 145 lks. dist.	•200
42.00	Foot of prairie.	
72.00	Road. S. W.	
80.00	Set post corner to Secs. 17, 18, 19 & 20 in prairie, to which there being no trees within reasonable distance, I raise a mound as per instructions.	
	East, on random between Secs. 17 & 20.	
21.00	Road E. & W.	
40.00	Set temporary ¼ Sec. post.	
73.50	Trail N. & S.	
79.40	Intersected N. & S. line, 12 links N. of post corner of Secs. 16, 17, 20 & 21., from which corner, I run, N.89*55*W., on true line between Secs. 17 & 20.	
39.70	Set ¼ Sec. post to which there being no trees within reasonable distance, I raise a mound with pile of stones	
79.40	To post corner of Secs. 17, 18, 19 & 20. Land, 2nd rate. Timber, A very few scattering oaks.	
	West, on random between Secs. 18 & 19.	
21.00	Summit of hill.	
32.50	Set meander post on South or left bank of Umpqua river, from which,	