

## County Surveyor's Record, Douglas County, Oregon

Subdivisions and Meanders of Umpqua River in Township 26 S.  
R. 4 W., W. M.

CHAINS	
	Land, 3rd rate, precipitous & rocky. Timber, A very few white & black oaks.
	West, on random between Secs. 7 & 18.
17.63	Set meander post on east or right bank of Umpqua River, from which, A W. Oak, 7 ins. dia., bears N.52*W., 39 lks. dist. A B. Oak, 8 ins. dia., bears S.45*E., 50 lks. dist.
22.24	Set meander post on west or left bank of Umpqua River, from which, An alder, 20 ins. dia., bears N.57*W., 47 lks. dist. A B. Oak, 12 ins. dia., bears S.78*W., 21 lks. dist.
40.00	Set temporary $\frac{1}{4}$ Sec. post.
56.00	Set meander post on east or left bank of Umpqua river from which, An Alder, 12 ins. dia., bears S.75*E., 18 lks. dist. An Ash, 4 ins. dia., bears N.15*W., 6 lks. dist.
61.12	Set meander post on west or right bank of Umpqua river from which, A Maple, 12 ins. dia., bears N.30*W., 3 lks. dist. A Maple, 3 ins. dia., bears S.15*W., 3 lks. dist.
78.58	Intersect township line, 12 lks. south of post corner of Secs. 7 & 18, from which corner I run, S.89*55'E., on true line between Secs. 7 & 18.
38.58	Set $\frac{1}{4}$ Sec. post from which, A W. Oak 25 ins. dia., bears N.75*W., 47 lks. dist. A W. Oak, 18 ins. dia., bears N.75*E., 54 lks. dist.
78.58	To post corner of Secs. 7, 8, 17 & 18. Land, 2nd rate, hilly, but good grazing for the most part, some 3rd rate, rocky land. Timber, Oak, and on the river, ash, maple and underbrush.