

Sub-divisions of T. 26 S., R. 5 W.

CHAINS		
	South 65 chains very hilly, part Oak Openings, part Brushy Timber.	
	North 15 chains runs in river.	
	Soil, 3rd rate.	
	S.89*54'E. on Random between Secs. 20 & 29.	
1.81		Var.at Temp. Post 19* 20'E.
80.26	Intersect N.&S. line 20 lks. N. of Sec. Cor.	
	N.89*45'W. on true line between Secs. 20 & 29.	
16.50	Top of spur, course N.&S.	+100
29.00	A Ravine, course N.W.	-250
40.13	Set $\frac{1}{4}$ Sec. post, from which	+150
	A Pine, 36 ins. diam. bears S.13 $\frac{1}{2}$ *W. 5 $\frac{1}{3}$ lks.	
	A. Y. Oak 12 ins. diam. bears N.52 $\frac{1}{2}$ *W. 275 lks.	
	Var.17*20'E.	
45.50	A trail, course N.E.&S.W.	-80
50.00	A ravine, course North.	-50
61.50	Top of ridge, N.20*E.&S.20*W.	+300
75.00	Foot of hill and enter low brushy bottom, course	
	N.20*E.&S.W.	
		-600
78.46	Intersect right bank of North Umpqua, and set Meander post, from which	
	A Maple 6 ins. diam. bears N.24*E. 27 lks.	
	An Ash 20 ins. diam. bears S.22*E. 42 lks.	
80.26	Sec. Cor. in river.	
	Land, this Mile is very hilly.	
	Timber, Oak, Laurel, with some Fir and Pine.	
	Soil, 3rd rate.	
	N.89*43'W. on random between Secs. 19 & 30.	
	Var.19*20'E.	
	Beginning at a point West of Meander post on left bank	
	Secs. 20 & 29. Thence measured S.10*E. 188 lks. Base.	
	Thence a flag 152 lks. East of Sec. Cor. (in river)	