

Survey of the Sub-divisions and Meanders of T. 26 S., R. 6 W.

CHAINS	. West to right bank of river into line.
45.31	Set temp. Meander post.
50.23	Intersect North boundary 56 lks West of Section Corner. S.24'W. on true line between S _{cs.} 5 & 6.
34.92	Intersect right bank of Umpqua river and set Meander post, from which A Y. Oak 20 ins. diam. bears N.39 ³ / ₄ *E. 58 lks. A W. Oak 20 ins. diam. bears N.20 ¹ / ₂ *W. 239 lks. Course of river N.35*W. Bank 20 feet high.
45.33	Set Meander post on left bank, from which A Y. Oak 24 ins. diam. bears N.58*W. 87 lks. A W. Oak 10 ins. diam. bears S.52*E. 73 lks.
80.23	To Section Corner. North of river hilly oak openings, Soil 3rd rate. South of river level oak openings, soil 2nd rate.

Meanders of Umpqua River, T. 26.S., R. 6 W.

Beginning at a Meander post in North Boundary, of Township, thence on Right bank up stream.

Courses	Chains	Remarks
		In Sec. No. 6
S.31 ¹ / ₂ *E.	14.12	
S.35 ³ / ₄ *E.	12.15	Bank low and bushy.
S.28 ¹ / ₂ *E.	4.40	
S.37* E.	11.58	To meander post bet. Secs 5&6
		In Sec. No. 5
S.28* E.	21.15	
S.38* E.	7.20	
S.51 ¹ / ₂ *E.	10.60	
S.27 ¹ / ₂ *E.	6.60	Along at foot of steep hill.
S.12 ¹ / ₂ *E.	8.60	To Meander between Secs. 5 & 8.