

Meanders of Umpqua River T. 26 S., T. 6 W.

CHAINS

Courses	Chains	Remarks.
N.20 *E.	6.00	In Section No. 32 to junction of North and South Forks, thence up North Fork on left bank.
S.71 $\frac{1}{4}$ *E.	7.50	
East	10.42	Bank bushy timber, fir, maple, ash, etc.
N.80 *E.	6.30	
S.88 *E.	2.90	
N.83 *E.	19.83	Soil sandy and gravelly.
S.71 *E.	6.30	
S.44 $\frac{1}{4}$ *E.	4.90	Bank very brushy.
S.79 *E.	2.80	
N.86 *E.	3.75	Timber, fir ash, maple.
N.68 $\frac{1}{4}$ *E.	5.20	
N.73 *E.	4.90	
N.62 $\frac{1}{2}$ *E.	7.50	To Meander post between Secs. 32 & 33.

N.64 $\frac{1}{4}$ *E.	5.80	In Section No. 33.
N.71 *E.	14.50	Bank timbered with fir, maple, ash.
N.83 *E.	11.00	
N.81 $\frac{1}{2}$ *E.	11.50	Bank very bushy.
N.76 $\frac{1}{2}$ *E.	4.80	
N.79 *E.	17.10	
N.83 $\frac{1}{2}$ *E.	8.90	
N.62 $\frac{1}{4}$ *E.	2.90	
N.69 *E.	6.90	To Meander post between Secs. 33 & 34.

S.68 $\frac{3}{4}$ *E.	4.65	In Section No. 34.
N.78 $\frac{1}{2}$ *E.	7.90	
N.64 *E.	9.20	To Meander post Between Secs. 27 & 34.

N.51 $\frac{1}{4}$ *E.	5.80	In Section No. 27.
N.43 *E.	15.20	Bank low and sandy.