

67

Meanders of Umpqua River T. 26 S., R. 6 W.

CHAINS

| Courses | Chains | Remarks |
|-------------------------|--------|--------------------------------------|
| In Section No. 18. | | |
| N. 57 $\frac{1}{2}$ *E. | 1.70 | N. 17*E. to Woodfins house 800 lks. |
| N. 68 $\frac{1}{2}$ *E. | 5.80 | At 350 lks. Woodfins ferry landing. |
| N. 77 *E. | 7.16 | |
| N. 66 *E. | 11.00 | |
| N. 62 *E. | 11.83 | Bank low and sandy. |
| N. 49 *E. | 8.50 | |
| N. 8 *E. | 6.40 | |
| N. 33 $\frac{1}{2}$ *W. | 11.38 | |
| N. 24 *W. | 8.20 | |
| N. 13 $\frac{1}{2}$ *W. | 12.56 | Bank low and sandy. |
| N. 25 $\frac{1}{2}$ *W. | 11.71 | |
| N. 36 $\frac{1}{2}$ *W. | 12.40 | To Meander post between Secs. 7 & 18 |
| In Section No. 7. | | |
| N. 18 $\frac{1}{2}$ *W. | 3.20 | |
| North | 5.00 | |
| N. 22 *W. | 3.00 | |
| N. 5 *E. | 2.50 | Bank rocky and brushy. |
| N. 12 $\frac{1}{2}$ *E. | 7.90 | |
| N. 24 *E. | 5.60 | |
| N. 42 $\frac{3}{4}$ *E. | 2.90 | |
| N. 52 $\frac{1}{2}$ *E. | 4.10 | |
| N. 35 $\frac{3}{4}$ *E. | 7.15 | |
| N. 53 $\frac{1}{2}$ *E. | 11.67 | Along rocky bar. |
| N. 59 *E. | 3.00 | |
| N. 67 $\frac{1}{4}$ *E. | 14.75 | At foot of steep hill. |
| N. 72 *E. | 4.30 | |
| N. 65 *E. | 19.15 | |
| N. 82 $\frac{3}{4}$ *E. | 4.48 | To Meander post Between Secs. 7 & 8. |
| In Section No. 8. | | |
| N. 63 $\frac{1}{4}$ *E. | 7.62 | |
| N. 71 *E. | 9.20 | |
| N. 44 *E. | 8.50 | Along sandy and gravelly bar. |
| N. 4 $\frac{3}{4}$ *E. | 6.54 | To Meander post between Secs. 5 & 8 |

RECORDED
PER [unclear]
4/4/90