

County Surveyor's Record, Douglas County, Oregon

-33-

Retracement of West Bdy. of T. 26 S., R. 7 W., W.M.

CHAINS

South on west boundary of Sec. 31.

Va. 19°30'E.

5.40 Stream, 3 lks. wide, course NW.

21.00 Commenced descending.

40.15 Quarter post decayed. Witness trees all found. Made and set new Chinquapin post, the usual length and size, from which,

A Hemlock, 10 ins. diam., bears N.28°E., 26 lks. dist.

A Hemlock, 8 ins. diam., bears N.13°W., 40 lks. dist.

49.00 Stream, 6 lks. wide, course SW.

50.70 Stream, 2 lks. wide, course West.

68.95 Stream, 6 lks. wide, course SW.

80.30 Corner to townships 26 and 27 S., Rs. 7 and 8 W.

Post standing and in good condition. Witness trees---

Fir, 36 ins. diam., bears N.40°W., 93 lks. dist.

Fir, 24 ins. diam., bears S.32°W., 83 lks. dist.

Fir, 36 ins. diam., bears S.50°E., 4 lks. dist.

Cedar, 18 ins. diam., bears N.20°E., 102 lks. dist.

Retracement of Southern Boundary of T. 26 S., R. 7 W.
same Deputy and contract.

Commenced again on the south boundary of T. 26 S., R. 7 W. at SE. cor. sec. 33 and ran west on south bdy. sec. 33.

Va. 19°30'E.

11.00 Stream, 6 lks. wide, course SE.

40.00 Quarter post not found. Witness found. Made and set a new Hemlock post, usual length and size, from which the trees bore-----

A Black oak, 12 ins. diam., bears N.40°E., 25 lks. dist.

A Laurel, 20 ins. diam., bears S.89°W., 68 lks. dist.

49.00 Enter fir timber

80.00 Corner to secs. 32, 33, 4 and 5. Old post gone.