

County Surveyor's Record, Douglas County, Oregon

- 35 -

Retracement of Southern Bdy. of T. 26 S., R. 7 W., W.M.

CHAINS

- 40.00 Quarter post not found. Witness found. Made and set new Hemlock post, usual size and length, from which,
 A Fir, 40 ins. diam., bears N.70*E., 39 lks. dist.
 A Fir, 40 ins. diam., bears S.31*E., 41 lks. dist.
- 63.30 Stream, 6 lks. wide, course North.
- 79.00 Corner to townships 26 and 27 S., Ranges 7 and 8 W.
 July 2, 1881
-
- Subdivisions of T. 26 S., R. 7 W., W.M.
 as surveyed by Deputy surveyor, S.C. Flint, under
 contract No. 392, dated May 26, 1881
-
- Commenced at the SW. corner of Sec. 33, from which
 A Fir, 15 ins. diam., bears N.75*E., 18 lks. dist.
 A Fir, 15 ins. diam., bears N.67*W., 45 lks. dist.
 A Fir, 24 ins. diam., bears S.23*W., 75 lks. dist.
 A Fir, 18 ins. diam., bears S.89*E., 90 lks. dist.
- Thence North on true line bet. secs. 32 and 33.
 Va. 19 $\frac{1}{2}$ *E.
- 10.00 Summit of Coast Range of mountains
- 30.00 Commenced to descend
- 40.00 Set a Cedar post, 3 ins. sq., 3 ft. long, firmly in the ground for $\frac{1}{4}$ sec. corner, from which,
 A Fir, 12 ins. diam., bears S.53*E., 7 lks. dist.
 A Fir, 12 ins. diam., bears S.70*W., 14 lks. dist.
- 64.50 Creek, 2 lks. wide, course West.
- 80.00 Corner to secs. 28, 29, 32 and 33, from which,
 A Laurel, 5 ins. diam., bears S.40*E., 25 lks. dist.
 A Fir, 25 ins. diam., bears S.60*W., 28 lks. dist.
 A Laurel, 5 ins. diam., bears N.70*W., 18 lks. dist.
 A Laurel, 5 ins. diam., bears N.40*E., 27 lks. dist.
- Land, 3rd rate.
 Timber, Hemlock, Fir, Cedar.
-
- East on random line between secs. 28 and 33
 Va. 19 $\frac{1}{2}$ *E.
- 15.17 Fir tree, 30 ins. diam.
- 23.20 Summit of coast range mountain.
- 25.00 Commenced to descend.
- 40.00 Set temporary $\frac{1}{4}$ sec. post.