

Subdivisions of T. 26 S., R. 7 W., W.M.

CHAINS

- 79.50 Intersected line 24 lks. N. of cor. to secs. 27, 28, 33 and 34, in swamp. Old post down; witness trees found. Made and set new post. Thence I ran N.89*50'W. on true line between secs. 28 and 33 with same variation.
- 39.75 Set a hemlock post for $\frac{1}{4}$ sec. post, from which,
A Laurel, 12 ins. diam., bears S.12*W., 30 lks. dist.
A Fir, 15 ins. diam., bears N.15*E., 12 lks. dist.
- 79.50 Corner to secs. 28, 29, 32 and 33.
Land, 3rd rate, very steep, rocky and broken.
Timber, Fir, Hemlock, Cedar, Chinquapin, Maple and Ash.
Underbrush, Laurel, Hazel.

July 18th, 1881

North on true line bet. secs. 28 and 29

Va. 19 $\frac{1}{2}$ *E.

- 40.00 Set $\frac{1}{4}$ sec. post, a Laurel, 3 ft. long, 3 ins. sq., firmly in the ground, from which,
A Laurel, 4 ins. diam., bears N.65*W., 8 lks. dist.
A Laurel, 6 ins. diam., bears S.25*E., 33 lks. dist.
- 50.50 Began to descend towards canyon.
- 56.46 Creek, 10 lks. wide, course West.
- 80.00 Corner to secs. 20, 21, 28 and 29. Set a Cedar post 40 ins. long and 4 ins. sq. firmly in the ground, from which,
A Fir, 36 ins. diam., bears S.25*E., 6 lks. dist.
A Fir, 14 ins. diam., bears N.85*E., 30 lks. dist.
A Fir, 36 ins. diam., bears N.40*W., 46 lks. dist.
A Fir, 36 ins. diam., bears S.35*W., 65 lks. dist.
- Land, 2nd rate.
Timber, Cedar, Hemlock, Fir, Dogwood, Laurel and Chinquapin.
Underbrush on 1st one-half mile terrible to get through.