

County Surveyor's Record, Douglas County, Oregon

-50-

Subdivisions of T. 26 S., R.7 W., W.M.

CHAINS

Land, 3rd rate, broken and rocky.
 Timber, Fir, Hemlock, Cedar, Maple, and Laurel.
 Undergrowth, Fir, Laurel, Hazel, and Vine-maple.

July 30, 1881

East on random bet. secs. 5 and 8

Va. $19\frac{1}{2}^{\circ}$ E.40.00 Set temp. $\frac{1}{4}$ post.

41.00 Summit of ridge, course NW.

47.28 Cliff or rocks. Offset, 300 lks. north, then 200 lks.

49.28 East, thence back 300 lks. to line again

79.20 Intersect line 14 lks. south from corner to secs.

4, 5, 8 and 9. Thence I ran $S.89^{\circ}54'W.$ on true line
 bet. secs. 5 and 8.

39.60 Set Hemlock post for $\frac{1}{4}$ sec. cor, 3 ft. long and 4 ins.
 sq. from which,

A Fir, 24 ins. diam., bears $S.75^{\circ}E.$, 12 lks. dist.

A Fir, 30 ins. diam., bears $N.20^{\circ}W.$, 25 lks. dist.

79.20 Corner to secs. 5, 6, 7, and 8.

Land, 3rd rate. The East part of this mile (from
 summit) is exceedingly rough and rocky.

Timber, Hemlock, Fir, Cedar, Laurel, Maple and Ash.

Undergrowth, Fir, Laurel, Vine-maple and Hazel.

West on random bet. secs. 6 and 7

Va. $19\frac{1}{2}^{\circ}$ E.40.00 Set temp. $\frac{1}{4}$ post.

45.25 Stream, 3 lks. wide, course SW.

63.45 Ridge or spur, course SW.

80.80 Intersect west boundary of township, 15 lks. north
 from corner to secs. 6, 7, 1 and 12. Thence, I ran
 $N.89^{\circ}54'E.$ on true line, bet. secs. 6 and 7.

40.80 Set Fir, post for $\frac{1}{4}$ sec. cor, 3 ft. long, 5 ins. sq.
 from which,

A Laurel, 12 ins. diam., bears $S.30^{\circ}E.$, 25 lks. dist.