

County Surveyor's Record, Douglas County, Oregon

51

Subdivisions of T. 26 S., R. 7 W., W.M.

CHAINS

A Laurel, .14 ins. diam., bears N.15*W., 55 lks.
dist.

80.80 Corner to secs. 5, 6, 7 and 8.

Land, 3rd rate.

Timber, Hemlock, Fir, Cedar, Laurel, Chinquapin and
Maple.

Undergrowth, Fir, Laurel, Vine-maple, Hazel and Salal.

Aug. 1st, 1881

North on random bet. secs. 5 and 6

Va. 19 $\frac{1}{4}$ *E.

31.50 Summit of ridge, E. and W.

40.00 Set temp. $\frac{1}{4}$ post.

57.00 Branch of Hubbard Creek, 8 lks. wide, Course NW.

62.50 Creek, 5 lks. wide, course West.

80.05 Intersected North boundary of township, 96 lks. East
from corner to secs. 5, 6, 31 and 32. Thence I ran
S.0*41'E. on true line bet. secs. 5 and 6.

40.05 Set fir post for $\frac{1}{4}$ sec. cor, 3 ft. long, 4 ins. sq.
from which,

A Fir, 36 ins. diam., bears N.80*W., 2 lks. dist.

A Fir, 20 ins. diam., bears S.75*E., 6 lks. dist.

80.05 Corner to secs. 5, 6, 7 and 8.

Land, 3rd rate. This mile is almost one deep canyon,
going down at one end and up at the other.

Timber and undergrowth about the same as we have had
before.

Aug. 2nd 1881.

This township is similar in all respects to T.27 S.,
R. 7 W., containing the coast range of mountains,
through it's full length north and south. Very
broken and precipitous. The height of the range
cannot be less than, from 8 to 1200 feet.