

Subdivisions, of T. 26 S., R. 8 W.

CHAINS

Land, mountainous, rough and rocky.

Soil, 4th rate.

Timber, fir, hemlock, and cedar, nearly all dead.

Undergrowth, mountain balm, willow, and arrow-wood.

Mountainous land or covered with dense undergrowth

for 79.86 chs.

Sept. 30, 1896.

No lat. taken this day, the sky being overcast with

clouds during noon hour's.

N.0*02'W. bet. secs. 21 and 22.

Va.20*16'E.

Ascend.

8.00 Summit of spur, 80 ft. above cor. bears E. and W.

Descend.

40.00 Set fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on W. face, from which

A fir, 8 ins. diam., bears N.51'E., 88 lks. dist., marked $\frac{1}{4}$ S B T.

A fir, 8 ins. diam., bears N.44*W., 90 lks. dist., marked $\frac{1}{4}$ S B T.

48.50 A fir, 48 ins. diam. on line marked with 2 notches on N. and S. sides.

64.30 Lake Creek, 15 lks. wide, course W. 700 ft. below spur.

Ascend.

74.00 A fir, 36 ins. diam. on line, marked with 2 notches on N. and S. sides.

76.00 Summit of spur, 150 ft. above creek, bears NE. and SW.

Descend.

78.50 A small branch, course SW. 50 ft. below spur.

80.00 Set a fir post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for the cor. to secs. 15, 16, 21, and 22. marked T 26 S S 15 on NE, R 8 W S 22 on SE, S 21 on SW, S 16 on NW. faces, with 3 notches on S. and E edges.

See corrective notes to follow.