

County Surveyor's Record, Douglas County, Oregon

4725
85

Resurvey of the E. Bdy. of T. 26 S., R. 9 W.

CHAINS		
	<p>A hemlock, 9 ins. diam., bears S.89*30'E., 144 lks. dist., marked $\frac{1}{4}$ S B T.</p> <p>A maple, 18 ins. diam., bears N.28*45'W., 69 lks. dist., marked $\frac{1}{2}$ S B T.</p> <p>From this cor. the old $\frac{1}{4}$ sec. cor. which was a post, now rotted away, or otherwise destroyed. The cor. point being witnessed as described by the Surveyor General, bears S.13*45'E., 232 lks. dist. I obliterate the marks on the old bearing trees.</p>	
47.50	Top of spur, course E.	+95
49.35	Cedar creek, 90 lks. wide, runs SE.	-90
56.00	Ascend hill, bears NW. and SE.	
58.50	Top of spur, course W.	+60
61.07	Cedar Creek, 80 lks. wide, runs W.	-50
65.00	Ascend steep hill, bears NE. and SW.	
77.00	Top of spur, course SE.	+250
80.00	<p>Set cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for cor. of secs. 1, 6, 7, and 12, marked T 26 S S 6 on NE., R 8 W S 7 on SE., S 12 on SW. and S 1 on NW. faces, with 1 notch on N. and 5 notches on S. edges, from which</p> <p>A hemlock, 20 ins. diam., bears N.35*E., 19 lks. dist., marked T 26 S R 8 W S 6 B T.</p> <p>A hemlock, 12 ins. diam., bears S.2*15'E., 37 lks. dist., marked T 26 S R 8 W S 7 B T.</p> <p>A cedar, 12 ins. diam., bears S.28*30'W., 47 lks. dist., marked T 26 S R 9 W S 12 B T.</p> <p>A fir, 24 ins. diam., bears N.40*W., 23 lks. dist., marked T 26 S R 9 W. S 1 B T.</p> <p>From this cor. the old cor. which is a post, still standing and witnessed as described by the Surveyor General, bears S.13*45'E., 1.43 chs. dist. I destroy the post and obliterate the marks on the four trees described as bearing trees.</p> <p>Land, mountainous.</p> <p>Soil, 2nd rate.</p>	