

Resurvey of the E. Bdy. of T. 26 S., R. 9 W.

CHAINS		
	Timber, fir, cedar, hemlock, maple and laurel; dense undergrowth.	
	Mountainous or heavily timbered land, or land covered with dense undergrowth, 80.00 chs.	
N.0*6'W. on a true line bet. secs. 1 and 6.		
Va.19*15'E.		
1.05	Ravine, course E.	-20
5.00	Top of spur, course E.	+75
7.50	Ravine, course E.	-60
9.25	Top of spur, course E.	+50
10.75	Ravine, course E.	-50
12.50	Top of spur, course E.	+35
12.80	Spring branch, 1 lk. wide, runs E.	-40
18.80	Spring branch, 1 lk. wide, runs E.	
32.00	Spring branch, 1 lk. wide, runs E.	
37.35	Brook, 4 lks. wide, runs E.	
40.00	Set cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S. on W. face, from which	+40
	A fir, 40 ins. diam., bears S.59*E., 39 lks. dist., marked $\frac{1}{4}$ S B T.	
	A fir, 40 ins. diam., bears S.53*30*W., 39 lks. dist., marked $\frac{1}{4}$ S B T.	
	From this cor. the old $\frac{1}{4}$ sec. cor. which is a post much decayed, bears N.34*W., 21 lks. dist. I destroy the post and obliterate the marks on the old bearing trees.	
44.25	Spring branch, 1 lk. wide, runs E.	-40
47.50	Spring branch, 1 lk. wide, runs E.	
50.00	Top of spur, course E.	+100
58.50	Brook, 5 lks. wide, runs SE.	-100
59.00	Top of left bank of Brook, bears NW. and SE.	+30
60.50	Begin steep ascent, bears NW. and SE.	
81.70	The old cor. of Tps. 25 and 26 S., Rs. 8 and 9 W. which is a post much decayed but bearing the Surveyors	