

County Surveyor's Record, Douglas County, Oregon

-30-

Subdivision of T. 26 S., R. 9 W.

CHAINS

	N.89°43'E., on a random line bet. secs. 22 and 27.	
40.00	Set temp. $\frac{1}{4}$ sec. cor.	
80.36	Intersect N and S line 29 lks. N of the cor. of secs. 22, 23, 26, and 27.	
	Thence I run	
	S.89°56'W., on a true line bet. secs. 22 and 27.	
4.35	Ravine, course SE.	-40
14.85	Top of ridge, bears N and S.	+50
37.10	Spring branch 2 lks. wide, runs NW.	-150
40.18	Set a sand stone 15x12x10 ins. 10 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N face, from which	
	A cedar, 13 ins. diam., bears S.60°E., 36 lks. dist. marked $\frac{1}{4}$ S, B.T.	
	A cedar, 26 ins. diam., bears N.47°W., 88 lks. dist. marked $\frac{1}{4}$ S, B.T.	+40
41.35	Top of spur, course NW.	+25
43.85	Spring branch, 1 lk. wide, runs NW.	-60
60.35	Top of ridge, bears NW and SE.	+125
64.85	Spring branch 1 lk. wide, runs NW.	-80
70.35	Top of spur, course NW.	+50
77.10	Brook 2 lks. wide, runs NW.	-100
79.10	Brook 2 lks. wide, runs N.	
80.36	The cor. of secs. 21, 22, 27, and 28.	
	Land, mountainous.	
	Soil, 2nd rate.	
	Timber, fir, hemlock, cedar, yew, and maple.	
	Undergrowth, dense.	
	Mountainous and heavily timbered land, or land covered with dense undergrowth, 80.36 chs.	
	September 29, 1896.	
	At the cor. of secs. 21, 22, 27, and 28	
	Thence I run	
	N.0°8'W., bet. secs. 21 and 22.	

Var. 19°15'E.