

## County Surveyor's Record, Douglas County, Oregon

-35-

Subdivision of T. 26 S., R. 9 W.

CHAINS		
	Soil, 2nd rate.	
	Timber, fir, hemlock, cedar, alder, maple, and laurel, mostly 2nd growth.	
	Line runs through old deadening caused by fires probably 50 or more years ago.	
	Undergrowth, dense.	
	Mountainous or heavily timbered land, or land covered with dense undergrowth, 80.40 chs.	
	June 21, 1897.	
	At the cor. of secs. 9, 10, 15, and 16.	
	Thence I run	
	N.0°8'W., bet. secs. 9 and 10.	
	Var. 19°30'E.	
	Descend from cor. along NE slope.	
14.20	Spring branch 3 lks. wide, runs NE	-250
28.00	Leave deadening; enter heavy green timber, bears NE and W.	
30.00	Top of ridge, bears NE and SW	+500
40.00	Set myrtle post 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S on W face	-100
	from which	
	A myrtle, 6 ins. diam., bears S.20°E., 24 lks. dist. marked $\frac{1}{4}$ S, B.T.	
	An alder, 16 ins. diam., bears S.30°W., 24 lks. dist., marked $\frac{1}{4}$ S, B.T.	
41.25	Begin steep descent, bears NE and SW.	
58.23	Coos River 120 lks. wide, runs SW, and ascend	-750
68.75	Top of ridge, bears NE and SW	+225
80.00	Set maple post 3 ft. long, 3 ins. sq., 24 ins. in the ground for cor. of secs. 3, 4, 9, and 10, marked	-150
	T. 26 S, S 3 on NE, R. 9 W, S 10 on SE, S. 9 on SW and S. 4 on NW faces, with 5 notches on S and 3 notches on E edges, from which	