

Sixth Standard Parallel ^{South} of T. 27 S., R. 1 W. as surveyed
 by Samuel C. Flint, Deputy
 Surveyor, under contract No. 473, dated June 5, 1883.

CHAINS	
	<p>I began at the standard cor. to Tps. 27 and 28 S., Rs. 1 and 2 W. which is a post, 4 ins. sq., marked S C T 27 S on N., R 1 W S 31 on E. and R 2 W S 36 on W. faces with 6 notches on N., E. & W. edges,</p> <p>Thence I run</p> <p>East, on S. bdy. of Sec. 31.</p> <p style="text-align: right;">Var. 18°35'E.</p>
0.20	Enter heavy dense brush.
13.91	Offset S. 150 lks. to avoid rocky bluff.
23.67	Came back to line again.
40.00	<p>Set post 44x4 ins. firmly in the ground for stan. $\frac{1}{4}$ sec. cor. marked S. C. on N. & S. faces, from which</p> <p style="padding-left: 40px;">A fir, 36 ins. diam., bears N.62°E. 9 lks. dist. marked S C $\frac{1}{4}$ S B T.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears S.10°E. 31 lks. dist. marked S C $\frac{1}{4}$ S B T.</p>
71.80	Stream, 5 lks. wide, course SE.
72.00	Ascend hill.
80.00	<p>Set post 48x4 ins. firmly in the ground for stand. cor. to secs. 31 & 32 marked S C T 27 S R 1 W on N., S 32 on E. and S 31 on W. faces, with 5 notches on the E. and 1 notch on W. edges, from which</p> <p style="padding-left: 40px;">A fir, 14 ins. diam., bears N.18°E. 77 lks. dist. marked T 27 S R 1 W S 32 B T.</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears N.25°W. 63 lks. dist. marked T 27 S R 1 W S 31 B T.</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears S.35°W. 15 lks. dist. marked S B T.</p> <p>Land, 3rd rate.</p> <p>Timber, fir, hemlock, spruce, & pine.</p> <p>Underbrush, thick fir & hemlock.</p> <p>Rough & rocky.</p>