

## 6th Stan. Par. South of T. 27 S., R. 1 W.

CHAINS

East, on S. bdy. of sec. 32.

Var. 19°E.

2.80 Spring branch, 2 lks. wide, course S.

40.00 Set post 40x4 ins. firmly in the ground for stan.  $\frac{1}{4}$  sec.

cor. marked S. C. on N. &amp; S. faces, from which

A fir, 26 ins. diam., bears N.35°W. 102 lks. dist.

marked S C  $\frac{1}{4}$  S B T.

A fir, 5 ins. diam., bears S.10°W. 29 lks. dist.

marked S C  $\frac{1}{4}$  S B T.

53.50 Summit of mountain.

54.00 Descend mountain.

80.00 Set post 48x4 ins. firmly in the ground for stan. cor. to

secs. 32 &amp; 33 marked S C T. 27 S R 1 W on N., S 33 on

E. and S 32 on W. faces, with 4 notches on the E. and

2 on W. edges, from which

A fir, 15 ins. diam., bears N.28°E. 129 lks. dist.

marked T 27 S R 1 W S 33 B T.

A fir, 7 ins. diam., bears N.28°W. 97 lks. dist.

marked T 27 S R 1 W S 32 B T.

A fir, 8 ins. diam., bears S.3°W. 8 lks. dist.

marked S B T.

Land, 3rd rate.

Timber, fir, hemlock, spruce &amp; pine.

Underbrush, thick vine maple, elk and cinnamon.

Mountainous, rough and rocky.

June 23, 1883.

East, on S. bdy. of sec. 33.

Var. 18°30'E.

20.00 Enter bottom.

38.00 Leave bottom.

40.00 Set post 44x4 ins. firmly in the ground for stan.  $\frac{1}{4}$  sec.

cor. marked S C on N. &amp; S. faces, from which