

6th Stan. Par. South of T. 27 S., R. 1 W.

CHAINS

Land, 4th rate--rough & mountainous.
 Timber, fir, hemlock & pine.
 Thick underbrush of hemlock & pine.

General Description

Of the South boundary of T. 27 S., R.1 W. running east.
 This line passes through a very rough, rocky and broken section of country. The ridges are sharp and canyons deep and rugged. The land will average about 3rd rate. The topography of the country on the S. of line as well as that on the north as far as observable is similar to the country over which the line passes.
 The timber, fir, hemlock, spruce and sugar pine is abundant and of good quality.
 Underbrush, thick vine maple, fir, cinnamon and hazel.

East, on S. bdy. of Sec. 36.

Var. 18*45'E.

- 24.20 Summit of ridge, N. & S.
- 40.00 Set post, 44x4 ins. firmly in the ground for stan. $\frac{1}{4}$ sec. cor. marked S C on N. & S. faces, from which
 A fir, 14 ins. diam., bears N.70*W. 50 lks. dist. marked S C $\frac{1}{4}$ S B T.
 A fir, 16 ins. diam., bears S.45*W. 21 lks. dist. marked S C $\frac{1}{4}$ S B T.
- 44.07 Stream, 8 lks. wide, course N.
- 50.50 Summit of ridge, N. & S.
- 74.75 Stream, 15 lks. wide, course N.
- 80.00 Set post 48x4 ins. firmly in the ground for stan. cor. to Tps. 27 S., Rs. 1 W. & 1 E. marked S C T 27 S on N., R 1 E. S 31 on E. and R 1 W S 36 on W. faces--6 notches on N., E. & W. from which
 A laurel, 8 ins. diam., bears N.25*E. 26 lks. dist. marked T 27 S R 1 E S 31 B T.