

Resurvey of a Portion of West Bdy. of T. 27 S., R. 1 W.

CHAINS	Thence leave heavy timber and enter scattering timber, bears E. and W.
72.50	Top of ascent. Thence over bench land. Leave scattering timber and enter heavy timber, bears SE and NW.
88.90	The cor. of secs. 1, 6, 7 and 12. Land, mountainous. Soil, stony and 3rd rate. Timber, fir, pine, hemlock and cedar. Undergrowth, laurel and willow. Mountainous or heavily timbered land or land covered with dense undergrowth, 88.90 chs.
<u>Retracement of the West Bdy. of sec. 6.</u>	
45.10	From the cor. of secs. 1, 6, 7 and 12, I run North, retracing old line bet. secs. 1 and 6. Over bench land through heavy timber and dense undergrowth. Old qr. sec. cor., bears E. 10 lks.
49.25	Spring branch 1 lk. wide, course W.
52.00	Leave bench land. Descend, bears E. and W.
77.00	Foot of descent.
77.75	Creek 25 lks. wide, course W.; clear swift water. Ascend.
84.75	The cor. of Tps. 26 and 27 S., Rs. 1 and 2 W., which is a post greatly decayed and witnessed as described by the Surveyor General. In the place of the decayed stake, I set a basalt stone 15x12x8 ins., 10 ins. in the ground for cor. of Tps. 26 and 27 S., Rs. 1 and 2 W., marked with 6 notches on each edge. Land, mountainous. Soil, stony, 3rd rate.