

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 27 S., R. 1 W.

CHAINS

Timber, fir, hemlock, cedar and pine.

Undergrowth, laurel, vine maple and willow.

Mountainous or heavily timbered land or land covered with
dense undergrowth, 80.00 chs.

S.89*58'E. on a random line bet. secs. 22 and 27.

40.00 Set temp. $\frac{1}{4}$ sec. cor.80.24 Intersect N. and S. line 37 lks. S. of cor. of secs. 22,
23, 26 & 27.

Thence I run

S.89*46'W. on a true line bet. secs. 22 and 27.

Descend through heavy timber and dense undergrowth.

37.50 A creek, 40 lks. wide, course N.75*W.

Thence along hillside, bears E. & W.

40.12 The point for $\frac{1}{4}$ sec. cor. falls upon a rock in place, 2
x1x1 ft. above ground on which cut a cross (x) at the
exact cor. point for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. face,
from whichAn alder, 10 ins. diam., bears N.81 $\frac{1}{2}$ *E. 46 lks. dist.
marked $\frac{1}{4}$ S 22 B T.A cedar, 18 ins. diam., bears S.15*W. 17 lks. dist.
marked $\frac{1}{4}$ S 27 B T.

45.75 South bank of creek, course W.; thence down creek.

47.75 Leave creek, course N.75*W.

Ascend.

79.25 A perpendicular cliff, 50 ft. high, course N. and S.

80.24 The cor. of secs. 21, 22, 27 and 28.

Land, mountainous.

Soil, stony, 4th rate.

Timber, fir, hemlock, alder, and cedar.

Undergrowth, laurel, alder, willow and huckleberry.

Mountainous or heavily timbered land or land covered
with dense undergrowth, 80.24 chs.

July 19, 1902