

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 27 S., R. 1 W.

CHAINS

Ascend over precipitous land through heavy timber and dense undergrowth.

17.50 Top of ascent, thence over plateau.

39.65 Set a basalt stone, 24x14x5 ins., 18 ins. in ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on W. face, from which

A fir, 30 ins. diam., bears N.72°E. 65 lks. dist. marked $\frac{1}{4}$ S 5 B T.

A cedar, 14 ins. diam., bears N 40°W. 59 lks. dist. marked $\frac{1}{4}$ S 6 B T.

50.00 Descend over precipitous land.

79.65 The cor. of secs. 5, 6, 7 and 8.

Land, mountainous.

Soil, 4th rate.

Timber, fir, hemlock, pine, cedar and laurel.

Undergrowth, laurel and huckleberry.

Mountainous or heavily timbered land or land covered with dense undergrowth, 79.65 chs.

July 30, 1902.

General Description

This township is very mountainous. The soil is of a poor quality, with the exception of some small areas of bottom land along Little River.

It is covered throughout with a heavy growth of timber and with dense undergrowth. The southern and western parts abound with valuable fir and pine timber.

The township is well watered by Little River which runs through the middle portion, and by many small springs and brooks.

There are many settlers in the township.