

## County Surveyor's Record, Douglas County, Oregon

43

## Retracement of Subdivisions T, 27 S., R. 2 W.

CHAINS  
41.25

Creek, 10 lks. wide, course North.

65.00

Little River, 125 lks. wide, course South 10°W.

80.75

Intersect N and S line N of cor. of Secs. 3, 4, 9 and 10, which is a greatly decayed post and as the marks on post and bearing trees had been nearly obliterated by fire, I reestablish this cor. by setting in place of old post a Basalt stone, 16x10x6 ins., 12 ins. in the ground, marked with 5 notches on S and 3 notches on E edges, from which

A Fir, 16 ins. diam., bears N.31°E., 48 lks. dist., marked T 27 S R 2 W S 3 B T.

A Fir, 36 ins. diam., bears S.15°E., 30 lks. dist., marked T 27 S R 2 W S 10 B T.

A Maple, 12 ins. diam., bears S.48°W., 21 lks. dist., marked T 27 S R 2 W S 9 B T.

A Fir, 30 ins. diam., bears N.51½°W., 141 lks. dist., marked T 27 S R 2 W S 4 B T.

The course of the line from the ¼ Sec. cor. to the Sec. cor. is S.89°42'W., and the distance is 40.40 chs.

Land, rolling.

Soil, rocky, 3rd and 4th rate.

Timber, Fir, Pine and Cedar.

Undergrowth, young Fir and Vinemaple.

Heavily timbered land and covered with dense undergrowth.

80.85 chs.

July 17, 1905.

August 7, I reestablish the cor. of Secs. 5, 6, 7 and 8, which is a stone mound with remains of charred post in center, witnessed as described by the Surveyor General. The bearing trees having been killed by fire and marks on same nearly obliterated, I destroy all traces of old cor. and mark a cross (X) at exact point of old cor. on a point of bed rock 24x24x48 ins. above the ground, notches impracticable, I raise a mound of stone, 2 ft. base, 1½ ft. high W of cor., from which