

Retracement of Subdivisions T. 27 S., R. 2 W.

CHAINS

A Fir, 16 ins. diam., bears N.84°E., 141 lks.
dist., marked T 27 S R 2 W S 5 B T.

A Fir, 48 ins. diam., bears S.65°E., 137 lks.
dist., marked T 27 S R 2 W S 8 B T.

A Fir, 30 ins. diam., bears S.23½°W., 154 lks.
dist., marked T 27 S R 2 W S 7 B T.

A Fir, 8 ins. diam., bears N.31°W., 107 lks.
dist., marked T 27 S R 2 W S 6 B T.

Thence I retrace

East, bet. Secs. 5 and 8.

Over rolling land, through scattering timber and dense
undergrowth.

4.00 Summit of ridge, bears N and S.

Begin to descend.

36.50 Spring branch 5 lks. wide, course South.

39.70 Fall 26 lks. N of the ¼ Sec. cor. which is a post 3 ins.
sq., 1 ft. high, firmly set, marked and witnessed as
described by the Surveyor General.

The course of the line from the Sec. cor. to the ¼ Sec.
cor. is S.89°38'E., distance 39.70 chs.

79.10 Intersect N and S line 59 lks. N of cor. of Secs. 4, 5,
8 and 9, which is a post 4 ins. sq., 2 ft. high,
firmly set, marked and witnessed as described by the
Surveyor General.

The course of the line from the ¼ Sec. cor. to the Sec.
cor. is S.89°31'E., distance 39.40 chs.

Land, rolling.

Soil, rocky, 3rd and 4th rate.

Timber, Fir and Pine.

Undergrowth, young Fir and Hazel, covered with dense
undergrowth.

79.10 chs.

August 7, 1905.

At the cor. of Secs. 5, 6, 7 and 8 heretofore described.

Thence I retrace

N.89°51'W., bet. Secs. 6 and 7.