

Retracement of the East Boundary of T. 27 S., R. 3 W.

CHAINS	Over Mountainous land through dense timber and underbrush
40.48	The $\frac{1}{4}$ sec. cor. which is a post, firmly set, marked and witnessed as described by the Surveyor General, bears East 9 lks. dist. The course of this line is N.0°29'E. and the length is 40.48 chs.
81.15	The cor. of secs. 25, 30, 31 & 36 which is a post, firmly set, marked and witnessed as described by the surveyor general, and which I now change to refer to secs. 25 & 36, T 27 S., R 3 W only bears East 3 lks. dist. The course of this line from the $\frac{1}{4}$ sec. cor. is N.0°16'E. and the length is 40.67 chs.
	Land Mountainous
	Soil, 2nd. rate
	Timber, heavy Fir and Hemlock
	Dense undergrowth of little Fir and Hemlock
	Sky overcast at noon; lat. observation impossible
	September 25, 1911
	At the cor. of secs. 25 and 36
	Thence I run
	N.0°21'E., retracing E. bdy. of sec. 25
	Over Mountainous land through dense timber and underbrush
41.34	Intersect the $\frac{1}{4}$ sec. cor. which is a post firmly set, marked and witnessed as described by the Surveyor General and which I now change to refer to sec. 25, T 27 S., R 3 W., only
	The course of this line is N.0°21'E., and the length is 41.34 chs.
81.21	Intersect the cor. of secs. 19, 24, 25 and 30 which is a post firmly set; A Fir 24 ins. diam. marked T 27 S R 3 W S 25 B T alone remains of bearing trees, a heavy forest fire of 1911 having destroyed the timber, I now change this cor. to refer to secs. 24 and 25 T 27 S R 3 W only.
	The course of this line from the $\frac{1}{4}$ sec. cor. is N.0°21'E. and the length is 39.87 chs.
	Land Mountainous