

- 5

Extension Survey of Subdivision of T. 27 S., R. 2 W., W.M.

CHAINS

Ascend steep slope through dense timber and underbrush
exceptionally difficult to survey

22.00 Top of ridge, bears N & S

Descend

27.80 Creek, 1 lk. wide, course North

35.05 Creek, 2 lks. wide, course North

40.00 Set a Hemlock Post, 3 ft. long 4 ins. sq. 24 ins. in the
ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 24 on N and S 25 on
S face from which

A Fir, 55 ins. diam., bears N.22*30'E., 36 lks. dist.

Marked $\frac{1}{4}$ S 24 B T

A Fir, 18 ins. diam., bears S.57*30'E., 60 lks. dist.

Marked $\frac{1}{4}$ S 25 B T

Could not find Derricks $\frac{1}{4}$ sec. cor. after diligent search

43.50 Rangers trail to Red Butte, bears N and S

44.25 Creek, 3 lks. wide, course NW

Ascend through heavy timber and dense underbrush

75.20 Bourgeois fence, bears N & S

Ascend through clearing

79.00 Nebat's cabin, bears South 5 lks. dist.

Bourgeois Cabin, bears North 4 chs. dist.

79.01 Nebat's fence bears N & S

82.91 Intersect West boundary of T. 27 S., R. 1 W., 92 lks.

S.0*45'E., of cor. of secs. 19 & 30

At point of intersection, I set a Fir Post, 3 ft. long
4 ins. sq. 24 ins. in the ground for closing cor. of secs.
24 & 25 marked C C T 27 S R 2 W S on West, S 24 on N
and S 25 on S face with 2 grooves on S and 4 grooves on
N face from which

A Fir, 18 ins. diam., bears S.6*15'W., 119 lks. dist.

Marked T 27 S R 2 W S 25 B T

A Fir, 36 ins. diam., bears N.12*40'W., 80 lks. dist.

Marked T 27 S R 2 W S 24 B T

Land Mountainous

Soil, 1st. and 2nd. rate

Timber, heavy Fir, Hemlock, Cedar and Pine