

## County Surveyor's Record, Douglas County, Oregon

46

## Extension Survey of Subdivision of T. 27 S., R 2 W., W.M.

CHAINS

Dense undergrowth, little Fir, Hemlock, and vinemaple  
 Mountainous land, covered with heavy timber and dense  
 undergrowth and exceptionally difficult to survey, 82.91  
 chs.

Sky overcast at noon; observation for lat. impossible

October 2, 1911

At the cor. of secs. 23, 24, 25 & 26

Thence I run

N.0°01'W., bet. secs. 23 & 24

Descend ridge, through heavy timber and dense undergrowth  
 exceptionally difficult to survey

38.00 Creek, 15 lks. wide, course NE

Ascend

40.00 Set a Hemlock Post 3 ft. long, 4 ins. sq. 24 ins. in the  
 ground for  $\frac{1}{4}$  sec. cor., marked  $\frac{1}{4}$  S 23 on W and 24 on E  
 face from which

A Hemlock, 10 ins. diam., bears S.85°E., 32 lks. dist.

Marked  $\frac{1}{4}$  S 24 B T

A Yew, 8 ins. diam., bears N.80°W., 23 lks. dist.,

Marked  $\frac{1}{4}$  S 23 B T

At this cor. I set off 3°44'S., on the decl. arc., and  
 observe the sun on the meridian at noon; the resulting  
 lat. is 43°12'N.

43.75 Derricks  $\frac{1}{4}$  sec. cor. which I now destroy bears East 2.50  
 chs. dist.

73.00 Top of ridge, bears NE & SW

80.00 Set a Hemlock, <sup>post,</sup> 3 ft. long 4 ins. sq. 24 ins. in the ground  
 for cor. of secs. 13, 14, 23 & 24 marked T 27 S S 13 on  
 NE, R 2 W S 24 on SE, S 23 on SW, and S 14 on NW face with  
 3 notches on S and 1 notch on E edge from which

A Cedar, 14 ins. diam., bears N.88 $\frac{1}{2}$ °E., 27 lks. dist.

Marked T 27 S R 2 W S 13 B T

A Hemlock, 10 ins. diam., bears S.62°E., 14 lks. dist.

Marked T 27 S R 2 W S 24 B T

A Hemlock, 10 ins. diam., bears S.37°W., 7 lks. dist.