

County Surveyor's Record, Douglas County, Oregon

Extension Survey of Subdivisions of T. 27 S., R. 2 W., W.M.

CHAINS

dist., Marked T 27 S R 2 W S 27 B T
 A Cedar, 30 ins. diam., bears S.21*E., 39 lks. dist.,
 Marked T 27 S R 2 W S 34 B T
 A Fir, 34 ins. diam., bears S.21*30'W., 18 lks. dist.,
 Marked T 27 S R 2 W S 33 B T
 A Cedar, 30 ins. diam., bears N.11*30'W., 12 lks. dist.
 Marked T 27 S R 2 W S 28 B T

Derricks cor. for secs. 27, 28, 33 & 34, which I now destroy bears N.19*E., 3.00 chs. dist.

Land Mountainous

Soil, 1st. and 2nd. rate

Timber, heavy Fir, Hemlock, Cedar and Pine

Dense undergrowth of little Fir, Hemlock and rhododendron

Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey 80.00 chains

Sky overcast at noon; lat. observation impossible

October 7, 1911

At the cor. of secs. 27, 28, 33 & 34

Thence I run

West, on sectional correction line bet. secs. 28 and 33

Ascend ridge, through heavy timber and dense underbrush exceptionally difficult to survey

12.38 Top of ridge, bears North and South; Descend

14.31 Creek, 5 lks. wide, course North; Ascend

21.31 Top of ridge, bears NW and SE; Descend

28.31 Creek, 3 lks. wide, course NE; Ascend

40.00 Set a Cedar Post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for 1/4 sec. cor., Marked 1/4 S 28 on North and 33 on South face from which

A Cedar, 12 ins. diam., bears N.72*E., 23 lks. dist.,

Marked 1/4 S 28 B T

A Cedar, 30 ins. diam., bears South, 12 lks. dist.,

Marked 1/4 S 33 B T

At this cor. I set off 5*40'S., on the decl. arc. and observe